Safety & Health Committee Minutes

UPDATE
January 11th, 2017





PLEASE PUT BACK ON SAFETY BOARD WHEN DONE READING

Agenda:

- Call to Order
- Attendance/Confirm Quorum
- Introduce guests
- · Review of agenda
- Review minutes of previous meeting/errors/omissions
- Motion to accept previous minutes
- Review local stats and identify any possible trends
- Review previous month's incidents discussing the cause and recommended corrective actions
- Safety Framework Activity Review
- SOFA/Planned Peer Observation Review
- Workplace/Customer Inspection Review
- Safety Hazard Report Review
- Old Business
- New Business
- Miscellaneous/Comments
- Confirm minutes and closing comments
- Set next meeting Date/Time/Location

Meeting Called to Order By: Clayton Geekie 10:14

Safety Briefing:

- ✓ Emergency Services 9-1-1: Jody Mead
- ✓ **Fire Marshall:** Pat Nahmiash
- ✓ **First Aid:** Clayton Geekie
- ✓ AED: Jason E Ross
- ✓ Meeting Point: Muster Point by parking lot

Attendance Taken By: Vicki Martin

Errors/Omissions from Last Month's Minutes:

N/A

Motion to Accept Minutes as Submitted/Amended: Clayton Geekie Second: Terry Maser

Committee Members:

Name	Email	Phone #	Position	H&S Trained	Present At Meeting
Craig Ruff Supt Operations Calgary & AB South	craig_ruff@cpr.ca	403-969-3229	Co-Chair T&E Management	Yes	X
Clayton Geekie Locomotive Engineer	clayton_geekie@cpr.ca	403-866-5647	Co-Chair T&E TCRC RTE	Yes	Х
Jody Mead Conductor	jodymead67@gmail.com	403-878-9712	Alternate Co-Chair T&E TCRC RTE	Yes	Х
Patrick Nahmiash Locomotive Engineer	<u>lr322@shaw.ca</u>	403-458-1825	Member T&E TCRC RTE	Yes	X
Jason E Ross	jasone_ross@cpr.ca	403-581-0752	Member Mechanical UNIFOR		Х
Terry Maser	terry_maser@cpr.ca	403-581-0912	Member B&B		Χ
Vacant			Member TCRC MWED		
Brian Raby	brian_raby@cpr.ca	403-928-5500	Member S&C IBEW		
Rob McNulty T&E	rob_mcnulty@cpr.ca	403-581-3795	Member T&E Management		
Dan Magee Manager S&C Maintenance	dan_magee@cpr.ca	403-502-4293	Member Engineering Management		
Freeman Hickey Roadmaster-Brooks	freeman_hickey@cpr.ca	403-594-1455	Member Engineering Management		
Willie Davis Roadmaster-Maple Creek	willie_davis@cpr.ca	403-866-9955	Member Engineering Management		
Rob Dunn Asst. Dir. S&C	rob_dunn@cpr.ca	403-581-0937	Member Engineering Management		
Nicholas Smith Supvr Mechanical	nicholas_smith@cpr.ca	403-329-7723	Member Mechanical Management		
Vicki Martin General Clerk	vicki_martin@cpr.ca	403-528-5000	Recording Secretary	N/A	Х

Quorum: Majority of the membership is present, and at least 50% are unionized. Yes (7 members 6 unionized)

Guests:

Nil

Employees & Geographical Region WHSC Represents:

Craft Empl	oyees Represented	Subdivision Miles	# of Employees Represented	Building/Yards Represented	Customer Locations
Craft	WHSC Member(s)				
T&E TCRC RTE	Clayton Geekie Jody Mead (Alt) Patrick Nahmiash	Medicine Hat	200	Medicine Hat Yard	
Mechanical UNIFOR	Jason E Ross	Medicine Hat	2	Medicine Hat Yard	
Engineering	B&B-Terry Maser	Medicine Hat	4	Medicine Hat Yard	
TCRC MWED	Track-Willie Davis	Maple Creek Sub	12		
	Track-Freeman Hickey	Brooks Sub	13		
S&C IBEW	Brian Raby Chris Sokolowski	Brooks Maple Creek	16	Medicine Hat Maple Creek Gull Lake Bassano	

Prairie Region Stats 2017 vs 2016 YTD		&E irie)		eering West)		anical West)
(as of January 5 th , 2017-manually generated)	2017	Dec 8, 2016	2017	Dec 8, 2016	2017	Dec 8, 2016
Rule Violations						
FRA Train Accidents	0	6	0	2	0	0
Non FRA Train Accidents	1	73	0	47	0	12
FRA Personal Injuries	1	28	0	22	0	6
Non FRA Personal Injuries	0	42	0	42	0	16

Local Stats 2017 vs 2016 YTD	T	ķЕ	Engin	eering	Mech	anical
(as of January 10 th ,2017	2017	2016	2017	2016	2017	2016
Rule Violations	0	5	0	1	0	0
FRA Train Accidents	0	2	0	0	0	0
Non FRA Train Accidents	0	5	1	0	0	0
FRA Reportable Injuries	0	1	0	1	0	0
Non FRA Reportable Injuries	1	0	0	0	0	0

Date of Last Local Incidents/ Number of Day's since beginning of 2016	T&E	Date 2017	Engineering	Date 2017	Mechanical	Date 2017
Rules Violation	Nil	Nil	Nil	Nil	Nil	Nil
Train Accident	Nil	Nil	14	29-Dec-16	Nil	Nil

Personal Injury Nil	Nil	Nil	Nil

Recent/Last Incidents/Injury(s) Causes

- Personal Injuries:
- > Non-FRA
 - 1. January 2017 (T&E) RTE was climbing up unit and hook his thumb on the door. Trainmaster took employee to hospital for medical attention. Employee was able to return back to work.
 - > Non-FRA
 - 1. Nil
- Rules Violation:

Nil

- Train Accidents:
 - > FRA
 - 1. Nil
 - > Non-FRA
 - 1. December 29, 2016 (ES) Operator after inspecting equipment at site started to reverse to set off point. Track Unit derailed and operator discovered rear hy-rail not engaged. Cleared track using four wheel drive front hy-rail was rotated and rendered non-operational while clearing track. Employee was observed to be fit and aware and filled out Initial Incident report on Managers arrival. Damage was recorded and front hy-rail arms removed and employee returned the unit to yard in Medicine Hat. Cause: Rear hy-rail not engaged. Formal Investigation to follow.
- Vehicle Accidents

Nil

All Other Incidents

Nil

Safety Framework Activities Completed Last Month

- Engineering TBA
- Mechanical NIL
- > T&E- Workplace Inspection (Maple Creek Sub)
- > T&E Customer Industry Audits (Richardson Pioneer)

SOFA/Planned Peer Observations

Sw	itching Operation	s Fa	atal	ity	Ana	alys	is (SOF	FA)	SC	ORE	CA	RD												
		Ja	an	Fe	eb	М	ar	A	pr	М	ay	Jı	ın	Jı	ul	Aı	ıg	S	ер	0	ct	N	οv	De	ес
Т	otal SOFA Audits																								
	SOFA Lifesavers	R	S	R	S	R	S	R	S	R	S	R	S	R	S	R	S	R	S	R	S	R	S	R	S
#1	Secure equipment before action is taken																								
	Three point protection requested																								
	Three point protection applied and confirmed																								
	Equipment separated by 50 feet																								
	Engine and cars properly secured																								
	Engine / Cars must not be moved until 3- point protection has been properly removed by the employee who requested the 3-point protection																								
	Protect employees against moving equipment																								
#2	Protect employees against moving equipment																								
	Crews working on the same tracks have an understanding of the other's moves																								
	Movement at a speed that allows them to stop within half the range of vision																								

		Ja	an	F	eb	М	ar	A	pr	М	ay	Jı	ın	J	ul	Αι	ıg	S	ер	0	ct	N	ov	De	ec
Т	otal SOFA Audits																								
	SOFA Lifesavers	R	S	R	S	R	S	R	S	R	S	R	S	R	S	R	S	R	S	R	S	R	S	R	S
	Specific car lengths given for shove moves																								
	Shove moves protected by employee																								
	Test the effectiveness of the handbrake application.																								
#3	Discuss safety at the beginning of a job and when a job changes																								
	Job briefing held at beginning of shift																								
	Proper job briefing procedure is followed and pre-departure checklist is completed properly																								
	Additional job briefing conducted when conditions change																								
#4	Communicate before action is taken																								
	Engineer does not begin shove until after receiving specific distance																								
	Crew does not use a combination of hand and radio signals																								
	Proper radio procedure is followed including verbal confirmation																								
#5	Mentoring, coaching Employees																								
	Senior crew member reviews experience of co-workers																								

	Ja	an	F	eb	М	ar	A	pr	Ma	ay	Ju	ın	Jı	ıl	Αι	ıg	Se	ер	0	ct	No	v	D	ec
Total SOFA Audits																								
SOFA Lifesavers	R	S	R	S	R	S	R	S	R	S	R	S	R	S	R	S	R	S	R	S	R	S	R	
Senior crew member mentors co-worker(s)																								
Proper entraining/detraining																								
Replacement of keepers																								Ī
Switch alignment																								
Derails																								
Fouling other tracks																								T

Customer Industry Audits

Location	Date of Audit	Findings	Required Measures	Due Date	Responsible Party
Richardson Pioneer	January 2017	No issues	N/A	N/A	H&S Committee

Workplace Inspections

Location	Date of Audit	Findings	Required Measures	Due Date	Responsible Party
Maple Creek Maple Creek Sub	12-Jan-17	Derail on North side mile 84.8 needs a new lock.	New lock to be put into place.		Willie Davis
Medicine Hat Station	13-Dec-16	-No flooring in men's locker room west. West end door is broken on men's locker room door	See if flooring can be put into men's locker room		11-Jan-17 Email sent to Muhammed Pasha
Alyth Bunkhouse	25-Aug-16	-Blackout blinds required in all rooms- 11-Jan-17 Facilities will let us know next weekBathrooms require new shower heads 8-Nov-16 Should be completed within a month. Men's countertop laminate along the side needs replacement in right wing.	Janel McLaren from facilities is aware of all issues.		13-Dec-16 Pat Nahmiash to follow-up with Facilities Janel. 11-Jan-17 Pat Nahmiash to do follow-up with outstanding items.

Risk Assessments Completed:

Nil

Safety Hazard Reports

Hazard	Class	Reported	Date	Action Taken
Med Hat front and back side of the yard Lots of snow around station and sidewalks. Slipping hazard. Salt, chip, scrape, shovel	(A, B, C)	T&E	Reported 23-Dec-16 Received in office on 4- Jan-17	5-Jan-17 Contractor from Brooks clean up the front and back side of Med Hat Yard. 11-Jan-17 Checking for a better process for snow removal with ES.
Alyth Canron Crossing Due to snow and ice, crew bus not able to move off road to drop off crews @ Canron crossing. Unsafe stop on road. Pave/install proper parking pad and walkway if that location is to be used for crew change as was before.		T&E	10-Jan-17	from Randy Ashley "There a bulletin out that there is no driving on the grass. Crossing has been gone for a number of years and will lose total access as soon as Green line starts there coming this year The crew change area was at Glenmore." 11-Jan-17 On going 29-Jan-17 (Update) There are no change-offs on at Canron unless safe to do so. Alyth Trainmaster please note. (This can be moved to the closed items at next H&S meeting)

Health and Safety-Exception Reports

NITI

Old Business Review

Date	Old Business Description	Responsible	Date to Be
Identified		Person(s)	Resolved
12-May-16	Shepard – There is still issues with the repeater. Ed Tomlenovich informed that there will be on going issues because of the area. A way to try and pin point the issues is to take the schematics and mark were the main issues are. 8-Nov-16 Radio exchange program is put into place. Radios have been updated with all new Medicine Hat channels. "Narrow Frequency". A bulletin has been drafted. Once employees have new radios bulletin will be issued. 11-Jan-17 Check spreadsheet to see who still needs to exchange radio with new channels. A letter will be put into employee's pigeon hole.	Asst Supt Leth will email to appropriate dept. 12-Jul-16 Radio issues have decreased. 13-Dec-16 -ES Dan Magee to check on the repeaterTM Chris Gingras to issue a bulletin on exchanging	On going

13-Sep-16	Lockers required at Alyth and Swift Current 8-Nov-16 Looking for 100 lockers more for Swift Current Comfort Inn. Clayton Geekie to send a list to Rob McNulty. 13-Dec-16 Locker list has been done. New lockers will be put into place. Looking for a timeline. Would like to have some bikes to be used in Swift Current. 13-Dec-16 Supt Calgary and Alberta South Craig Ruff will look into this. 11-Jan-16 Will look into the spring when weather	radios and provide a timeline. T&E	On going On going			
8-Nov-16	As per TSB watch list fatigue is an issue with RTEs. Crew members are being required to work over 10 hours after notice for rest has been given to be in and off duty in 10 hours which may cause fatigue. There have been several SHRs reported regarding these issues. Over hour violations were discussed at meeting. See below list for the breakdown of Over 10 Hour Violations: July there were 17; August there were 47; September there were 53; October there were 70; November there were 78; December there were 96. The below are the items being violated: Item 124 and Item 127.1 from the Labor Code and Violation of Company Corporate Policy. 11-Jan-16 Supt Operations Calgary and Alberta South Craig Ruff to review for next meeting. Timeline: 29-Jan-17. 29-Jan-17 Please see response dated January 29, 2017 from Supt Operations Calgary and Alberta South: "As discussed during the Health and Safety meeting, and as is apparent by those you have placed as copyholders, although not stated it appears you are referring to the contractual obligation to have crews in and off in 10 hours and not a specific incident where there was a safety concern relating to employee fatigue. Therefore I feel that this matter should continue to be handled through by the Local Chairmen and the Medicine Hat Health and Safety Committee continue to deal with matters pertaining to the Committee's mandate. I will consider this matter closed."	13-Dec-16 This will be escalated to Kevin Bishop from Supt Operations Calgary and Alberta South Craig Ruff	30 days. Response by 12-Jan-17			

New Business Review

Date Identified	New Business Description	Responsible Person(s)	Due Date			

Tabled/Escalated Items

Nil

Miscellaneous/Comments

 Bulletin No: INFO-AB-002-17 (T&E Availability Standard Canada) is in violation of The Government of Canada's definition of harassment and bullying. This can create an unsafe workplace. Labor code item 124 (General duty of employer). Labor code item 124 (General duty of employer) Every employer shall ensure that the health and safety at work of every person employed by the employer is protected.

Place and Time of Next Meeting:

Place: Medicine Hat Yard - Main Floor, Meeting Room

Date: Thursday, February 2, 2017

Time: 1000

Meeting Adjourned At: 12:14

Schedule 10 Tracking

		Jan.	Feb.	Mar.	Apr.	Мау	June	July	Aug.	Sept.	Oct.	Nov.	Dec.	TOTAL
Meetings	Regular	Х												
	Special	0												
Complaints	Received	0												
	Resolved	0												
	Unresolved	0												
Refusals to work	Received	0												
	Resolved	0												
	Unresolved	0												
Inquiries, Investigations and Inspections		0												
Programs, measures and procedures monitored		0												
Health and safety hazards	Identified	2												
	Resolved	1												
	Unresolved	1												
Injuries	Disabling injuries	0												
	Minor injuries	1												
	Time lost due to injuries	0												